CAPSULE SUMMARY CT-1129

Briscoe barn B is located on the east side of Mackall Road, immediately opposite Cage Road. Access is private. It is situated on a flat plain with fields all around. A farm road leads past the south facade of the barn. There is another barn further east, on the south side of the farm road, and a tenant house to the south. Briscoe barn B measures eighty-eight by twenty-eight feet and has a modern double aisle plan. All of the timbers are circular sawn and nailed with wire nails. The barn has a concrete block stripping shed to the east. The tier poles run in the same direction as the roof axis, an element which makes this barn unusual.

Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	e (indica	te preferred name)		
historic				
and/or common	Briscoe Bar	n B		
2. Loca	ition			
street & number	Mackall Rd	. (Maryland Route 265)	_	not for publication
city, town	t. Leonar	d × vicinity of	1e congressional district	
state MD		county	Calvert	
3. Clas	sificatio	n		
Category district × building(s) structure site object	Ownership public private both Public Acquisiti in process being consid not_applic	yes: restricted ered yes: unrestricted	Present Use X agriculture Commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Pro	perty (give names a	and mailing addresse	s of <u>all</u> owners)
name Cassan	dra Briscoe			
street & number			telephone n	0.: 586-1343
city, town St	. Leonard	state	and zip code MD 20	0685
5. Loca	ition of L	egal Descripti	on	
courthouse, regis	stry of deeds, etc.	Calvert County Courtho	use	liber
street & number		Main Street (MD 765)	folio	
city, town Prince Frederick		state MD		
6. Repr	esentati	on in Existing	Historical Surv	eys
title				
date			federal stat	e county loca
pository for su	rvey records			
city, town			state	

Condition		Check one	Check one		
excellent	deteriorated	_X_ unaltered	_X original s	site	
good	ruins	altered	moved	date of move	
fair	unexposed				

Survey No.

CT-1129

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

See Attachment.

7. Description

Period preh 1400 1500 1600 1700	nistoric 0–1499 0–1599 0–1699	archeology-historic agriculture architecture art	community planning	literature _ military _ music	
X 1900)_	communications	industry invention	politics/government _	transportation other (specify)
Specific	dates		Builder/Architect		
check:	aı	icable Criteria:A nd/or icable Exception:A		EFG	
	Leve:	l of Significance:	nationalstate _	_local	
Prepare support See A			f significance and a	a general statement of	history and

9. Major Bibliographical References

10. Geographi	cal Data		
Acreage of nominated property _ Quadrangle name ^{Broomes} Is1 UTM References do NOT com		rences	Quadrangle scale 1:24000
Zone Easting No	orthing	B Zone	Easting Northing
C		D	
Verbal boundary description	and justification		
List all states and counties f	or properties ove	rlapping state or co	ounty boundaries
state	code	county	code
11. Form Prep	ared By		
Tora William name/title	sen-Berry		
c/o Calvert County H organization Dept. of Pl	listoric Dis anning and	trict Commiss Z <u>oning</u> da	ion ate June 30, 1990
street & number Courthous	ie	te	elephone 535-1600
city or town Prince Fre	derick	st	tate MD

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to: Mary

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

7. DESCRIPTION CT-1129

Briscoe barn B is located on the east side of Mackall Road, immediately opposite Cage Road. It is situated on a flat plain, with fields all around. A farm road leads past the south facade of the barn. The barn is oriented on an east-west axis. There is another barn further east on the south side of the farm road, and a tenant house to the south. Briscoe barn B measures eighty-eight by twenty-eight feet and has a modern double aisle plan. All of the timbers are circular sawn, and nailed with wire nails. The barn has a concrete block stripping shed to the east. The tier poles run in the same direction as the roof axis, one element which makes this barn unusual.

The barn is divided into eight and twelve foot wide bays. are two sets of twelve foot wide double doors, centered along both the east and west gable ends. The barn frame is supported on concrete block masonry piers. The timbers are of medium weight and circular sawn. The posts are half-lapped and nailed to the plate. All of the other timbers are toe-nailed. All of the nails are Extensive bracing is used in this barn. There are down braces in each bay. There is an unusual internal cross-bracing arrangement. Cross-braces extend across the aisles on both sides of the barn, from the tie beam to the first tier pole level. These cross-braces are formed of double one by six inch timbers that have horizontal rails inserted between. The tier poles rest on these horizontal rails. The tier poles are peeled logs laid lengthwise along the same axis as the barn roof. The vertical distance between the tier poles is fifty inches.

Vertical wall siding with double plank side-hinged ventilation doors every four feet covers the exterior. The barn has a metal corrugated roof. Rafters are on four foot centers and rest on the plate. There is no false plate. The top plate is formed of a circular sawn three by four and one by four nailed together. There are windbraces on each diagonal. Three collars lend additional support to the roof.

There is a concrete block stripping room attached to the northeast corner of the barn. This stripping room measures sixteen feet wide and twenty-three feet long. Access is gained to it by a six foot wide double door on the south wall. It is heated with propane and totally enclosed with tight siding. There is an outhouse immediately to the south of it, near the east gable end of the barn.

8. SIGNIFICANCE CT-1129

This barn is architecturally significant for several reasons. It is one of the group of mid-late twentieth century tobacco barns with a long, narrow dual aisle plan, documented by this survey. This plan serves to accommodate vehicle drive-through. Typical of mid-late twentieth century tobacco barns, this barn has many ventilation doors and extensive bracing in the upper levels. The most unusual element of this barn is the fact that the tier poles are laid lengthwise along the same line as the roof axis. The reason for this variation from normal practice is unknown.

This barn also yields information regarding agricultural history in Southern Maryland. In February 1990, a tobacco barn survey was initiated in order to study the tobacco barns of Calvert County. Until fairly recently, tobacco was the most important farm crop of the county. More acreage was devoted to its cultivation than for both of the next most extensive farm products (corn and wheat). The barns and stripping houses related to this "Tobacco Culture" are widely recognized as the most common element on the rural These structures are also the most threatened, as the landscape. market for tobacco declines. They seem to have, at present, only limited capabilities for re-use. Many barns and stripping houses The purpose of this survey has been to gather now stand empty. information and document a wide sample of these structures before they disappear from the landscape.

Historical Period theme(s): ca. 1950-; Tobacco; Agriculture Geographical Organization: Western Shore Chesapeake Bay Calvert Cty MD


Chronological/Developmental Period: ca. 1950-Present


Resource Type(s): Tobacco Barn

#2102 - 5/16/90 - Sandra Briscoe, owner. 4 to Broome's Island, to Mackall. Barn is located on left side of Mackall Rd., immediately opposite Cage Rd. Very clean inside the barn -- still used to hang tobacco. Private ownership, occupied. TW sunny and warm weather. Unaltered, original site, excellent condition.

Located along farm road, tenant house to south. Open fields nearby.


Frame is supported on concrete block masonry piers. Timbers are medium weight and circular sawn. Posts are half-lapped and nailed to the plate. Other timbers are toe-nailed. All nails are wire. Internal bracing formed by double one by six inch timbers with braces inserted between. Vertical wall siding with double plank side-hinged ventilation doors every four feet covers the exterior. Metal corrugated roof. Rafters are on four foot centers and rest on the plate. There is no false plate. The top plate is formed of a circular sawn three by four and one by four nailed together. There are windbraces on each diagonal. Three collars lend additional support to the roof. The tier poles are peeled logs laid lengthwise along the same axis as the barn roof. There are poles down the central axis that are connected by internal crossbracing, with additional one by six inch horizontal boards connecting them. The vertical distance between the tier poles is There is a concrete block stripping room on the fifty inches. east side of the barn.





CT-1129





TORA L. WILLIAMSEN